

Wago PLC IP ping

```
Microsoft Windows [version 6.1.7601]
Copyright (c) 2009 Microsoft Corporation. Tous droits réservés.

C:\Users\charjac>ping 192.168.1.3

Envoi d'une requête 'Ping' 192.168.1.3 avec 32 octets de données :
Réponse de 192.168.1.3 : octets=32 temps=3 ms TTL=64
Réponse de 192.168.1.3 : octets=32 temps=2 ms TTL=64
Réponse de 192.168.1.3 : octets=32 temps=1 ms TTL=64
Réponse de 192.168.1.3 : octets=32 temps=2 ms TTL=64

Statistiques Ping pour 192.168.1.3:
    Paquets : envoyés = 4, reçus = 4, perdus = 0 (perte 0%),
    Durée approximative des boucles en millisecondes :
        Minimum = 1ms, Maximum = 3ms, Moyenne = 2ms

C:\Users\charjac>
```

Wago PLC Web interface

Web-based Management

Navigation

- Information
- Ethernet
- TCP/IP
- Port
- SNMP
- Watchdog
- Clock
- Security
- Modbus
- PLC
- Features
- IO config
- WebVisu

Status information

Coupler details

Order number	750-873/000-000
Mac address	0030DE0348B1
Firmware revision	01.01.06 (01)


Network details

IP address	192.168.1.3
Subnet mask	255.255.255.0
Gateway	192.168.1.1
Hostname	
Domainname	

Module status

State Modbus Watchdog:	Disabled
Error code:	3
Error argument:	0
Error description:	Commando error on terminal bus

Codesys communication parameters



Trying to login

